iX14 Spektrum™ AirWare™ Change Log
2023-Nov-21

Version 1.02.11

New Features

- Support for Spektrum Sky™ Remote ID
- Telemetry warning added for Turbine Max Pump Voltage
- New BNF model files added for new releases

Corrections & Improvements

- Taileron differential is now properly mixed to control surfaces
- Trim values are now processed properly when switching between flight modes for Aileron wing types
- Updated regulatory screens
- Turbine status messages are now properly displayed
- Dashboard screen properly orders telemetry screens to be displayed when gaps exist in the telemetry configurations
- German translation improvements
- Airware no longer crashes on Motor Curve screen when motor input is invalid
- Smart Battery telemetry now handles 0 Cycle data correctly
- "No Data" in ESC telemetry now handled properly

iX14 Spektrum™ AirWare™ Change Log

2023-Jan-23

Version 1.01.05

New Features

- The quick sleep button on the Sleep Mode screen has been changed from a press and hold to a swipe motion

Corrections & Improvements

- The system no longer shuts down when coming out of sleep mode
- While occurring rarely, corrupted models no longer occur when coming out of sleep mode
- Analog trim range now functions correctly with a 30% max trim value when step size set to one
- Turbine EGT is now available as an option on gauge and dashboard pages
- Sleep Mode dialog correctly shows state of Serial Port Power
- Accurate values are displayed on the Flight Log telemetry screen when %Range is selected
- Programmable Mixes are now shown in the Digital Switch Setup screen when a switch is assigned as source
- Values are now saved on Heli Cyclic/Thro Mixing screen
- Mixing screen operation has been updated to be more intuitive

iX20 Spektrum™ AirWare™ Change Log
2022-November

Version 1.00.03

Initial Release