

E-Maxx Bellcrank Installation

This bellcrank kit is a direct replacement for the E-Maxx model #3905. Refer to the exploded views included with your model for E-Maxx #3905 installation (exploded views are also available on Traxxas.com). This kit can also be used as part of an upgrade for nitro-powered Maxx models and E-Maxx model #3906. Note: There is an additional spacer included in this kit for other Maxx installations, refer to the exploded view, right*.

Additional hardware will need to be purchased to install this bellcrank on models other than E-Maxx model #3905. Refer to the parts list below.


5116 Ball bearings, blue rubber sealed (5x11x4mm) (2)\$3.50 2579 Screws, 3x15mm button-head machine (hex drive) (6)\$2.50

3642X Shoulder screws, Ultra Shocks (3x12 hex drive) (6)\$3.00

For questions or technical assistance, call:

1-888-TRAXXAS

(1-888-872-9927) (U.S. residents only)



WWW.TRAXXAS.COM

Traxxas, 1100 Klein Road, Plano, TX 75074, Phone: 972-265-8000, Fax: 972-265-8011, e-mail: support@Traxxas.com

KC1112 Form 4945INST Rev 071031

Covers Parts #4945



E-Maxx Belicrank Installation

This bellcrank kit is a direct replacement for the E-Maxx model #3905. Refer to the exploded views included with your model for E-Maxx #3905 installation (exploded views are also available on Traxxas.com). This kit can also be used as part of an upgrade for nitro-powered Maxx models and E-Maxx model #3906. Note: There is an additional spacer included in this kit for other Maxx installations, refer to the exploded view, right*.

Additional hardware will need to be purchased to install this bellcrank on models other than E-Maxx model #3905. Refer to the parts list below.

5116 Ball bearings, blue rubber sealed (5x11x4mm) (2)\$3.50 2579 Screws, 3x15mm button-head machine (hex drive) (6)\$2.50 3642X Shoulder screws, Ultra Shocks (3x12 hex drive) (6)\$3.00

For questions or technical assistance, call:

1-888-TRAXXAS

(1-888-872-9927) (U.S. residents only)

Nitro-Powered Maxx Models E-Maxx Model #3906 2576 3x8 BCS (to belicranks) Cut off left front (driver side) bellcrank post flush 3179 with frame rail. Lip faces bearing *4945 for nitro-powered Maxx use only 5116 5x11x4 BB to servo 4945 Lip faces bearing 4943 *4945 2742X 5x11x4 BB for 3906 E-Maxx use only 4944 to servo 2742X 2742X 2579 3X15 BCS 2742X 2537 3x12 GS 2579 3X15 BCS 5116 3x15 CCS 5x11x4 BB 3179 3X15 BCS 4944 **6** 5116 3x15 CM 5x11x4 BB 4944 2579 3X15 BCS 2550 3x8 CCS 3X12 SS 3x8 CM

3X12 SS

-WWW.TRAXXAS.COM